

PLANNING APPLICATIONS

PA	APP. NO.	APPLICANT	DEVELOPMENT
1.	PA26/02436	Mr and Mrs C Blackbourn	Proposed first floor extension to form bedroom and proposed balcony replacing existing Juliet balconies. The Nook, Parade Street, Penzance
2.	PA26/02093	Ben Sidgwick	Creation of 3 new parking spaces, formation of drainage trench and formation of granite hardstanding at communal entrance gateway. Coulsons Terrace, Penzance
3.	PA26/02627	Mrs Bull	Non-material amendment in relation to decision notice PA25/07591 dated 05.12.2025 to enlarge the ground floor door to the north east elevation 17 Florence Place, Newlyn
4.	PA26/01909	Mr Chris Bows CB Developments Ltd	Change of use from former cafe/hot food takeaway (formerly A5 use) and subdivision from one unit into a ground floor office and shop (Class E use). 10 Market Jew Street, Penzance
5.	PA26/02095	Messrs Matthew, Joe and David Berriman, Ivey and Coombs Rosevean Veterinary Practise	Replacement store shed Rosevean Vets, Rosevean House, Coombe Road, Penzance
6.	PA26/02065 LISTED BLDG	Ambrose and Celia Miller	The removal of area of painted concrete internal flooring and replacement with slate flooring. Keigwin, Keigwin Place, Mousehole

PLANNING APPLICATIONS

	APP. NO.		DEVELOPMENT & LOCATION
1.	PA26/01942 WINDOWS AND PA26/01943 LISTED BLDG	Mrs R Goff	Replacement windows. Cornerways, 5 Leskinnick Street, Penzance
2.	PA26/01995 WINDOWS & DOOR	Mr M Batty	Replacement windows and door. The Flat, 20 Mennaye Road, Penzance
3.	PA26/02352 LISTED BLDG	Environment and Planning Wales and West Utilities Dalcour Maclaren	Installation of a below ground Gas connection from the existing main in the pavement to the front (south) of the building (see Plan 24006703_PLN_SI_3.1). Alverne Restaurant, Alverne House, 30 Alverton Street, Penzance
4.	PA26/02506 TREES	Mr Gordon Mackay	Works to trees in a Conservation Area, T1 - Holm Oak (Quercus Ilex) - Crown Reduce by 2m. Trungle House, Trungle, Paul
5.	PA26/02510 TREES	Mr Tim Humphreys	Works to trees in a Conservation Area, namely 1) T1 – Willow – Dimantle and Remove. The tree in question is a small Willow in poor condition situated in the back yard of the property. It is in very poor overall condition and in direct contact with the granite wall, in a unsuitable position. The tree is of no amenity value. It requires removal to ground level. 3 Wellington Terrace, Penzance